



Leichtflugzeuge

COMCO
Düsen für Oberflächen

Service bulletin

SB 42-07 / 09-03

Subject:

Ejection opening, ballistic recovery system

Affected:

All IKARUS C42 / C42 B

Reason:

A placard with a danger sign indicating that pyrotechnical equipment is enclosed must be clearly visible on the ejection opening cover of the ballistic recovery system.

Action:

1. Attachment of the supplied placard to the middle of the ejection opening cover.
2. Filing of the relevant pages in the aircraft flight manual appendix: Location of the ballistic recovery system.
3. Completion of an appropriate certificate, a copy of which must be sent to the authorities with which the aircraft is certified.

Compliance:

Action must be taken by 31st October 2003 at the latest on all affected C42 / C42 B aircraft.

Mass and balance:

No alteration

Accomplishment instructions:

None